

## CERTIFICATE OF STABILITY

1. Name of the Building

SHAMIT SCHOOL GUT NO. 45, NAKSHATRAWADI PAITHAN ROAD AURANGABAD

I have personally visited the recently constructed above school building and critically inspected all the structural elements such as columns, beams and siab and also stidled the structural design of the building.

The structural design and construction of the above work is in conformity with the provisions of is 1893-1984-ISO, 13920-1993 for Earthquake resident design of structures ductile detailing if rainforced concrete structure subjected to seismic force and IS 4362-1993 for earthquake resistant design and construction of building.

I hereby certify that the above building is quite safe and stable and can be ounter & meture

accupied for its intended purpose of school building.

Sub - Divisional Enginees e.W. ( South) Sub Div.

Aurangabad

Principal SHAMIT SCHOOL Shamit Octozone Gut No. Nakshatrawadi, Aurangaba. Executive Engineer, Public Works Division, Aurangabad

